NFPA Journal

1994 INDEX

VOLUME 88 • NOS. 1–6

Key to references: 1.35 = Jan/Feb, pg. 35; 2.9 = Mar/Apr, pg. 9, etc.
1=Jan/Feb 2=Mar/Apr 3=May/Jun 4=Jul/Aug 5=Sept/Oct 6=Nov/Dec

A

ADVERTISING SUPPLEMENTS
Alarm, detection, and security systems, 1.80
Building construction and electrical products, 5.111
Extinguishing systems, 4.91
Fire service equipment, supplies, and services, 2.92
NFPA 1994 Annual Meeting exhibitors, 3.129
AEROSOL CONTAINERS
Hair spray used to ignite incendiary fire, 1.32
AIR CONDITIONERS
Fire spread by, 5.97
Operating noise may have masked alarm, 5.100
See also HVAC SYSTEMS
AIRCRAFT CRASH FIRES
Catastrophic, private passenger jet, California, Dec. 15, 1993, 5.106
Catastrophic, single-engine passenger plane, California, Nov. 26, 1993, 5.108
Jumbo passenger jet, Texas, April, 1993, 6.98
Military fighter-jet, New Mexico, Sept., 1993, 6.98
AIRCRAFT HANGAR FIRES
Kansas, July, 1993, 6.96
AIRPORTS
Catastrophic military aircraft fire, Wisconsin, Dec. 10, 1993, 5.106, 6.98
ALABAMA
Electric generating plant fire, June, 1993, 6.92
ALARM DELAYED
Dispatched to wrong address, 5.29
Employee(s) confirmed fire, 4.31, 6.89
Employee(s) evacuated patients, 4.29
Employee(s) fought fire, 2.27, 30, 5.30, 6.96, 97
Hotel room occupant had difficulty contacting front desk, 2.28
Lack of complete detection system, 5.102
Manual pull stations not operational, 5.95
911 call incomplete, 5.102
Occupant(s) fought fire, 1.31, 5.98, 102
Occupant(s) left site to report fire, 5.97
Passerby left site to report fire, 3.30
Reason unknown, 5.95
Smoke detector batteries removed, 1.30
ALARM SYSTEMS
Addressable systems, testing of, 2.41
Manual pull stations not operational, factor in catastrophic hotel fire, 5.95
Not a factor in catastrophic school fire, 5.105
Not a factor in fire on exterior of building, 6.35
Voice alarm system design guidelines, 1.50
ALARMS, FALSE
Delayed response to catastrophic fire, 5.98
ALCOHOL (BEVERAGE)
Factor in catastrophic dwelling fire, 5.97
Factor in fatal dwelling fires, 1.31
ALCOHOL (FUEL)
Spill ignited by light, 2.27
AMMONIA
Liquid refrigerant, factor in warehouse fire, 3.27
AMUSEMENT PARK FIRES
California, 1993, 3.28
APARTMENT BUILDING FIRES
Arkansas, 1993, 3.28
California, Nov., 1993, 6.89
Catastrophic, California, April 26, 1993, 5.96
Catastrophic, California, May 3, 1993, 5.95
Catastrophic, Michigan, Feb. 28, 1993, 5.95
Catastrophic, Minnesota, Nov. 10, 1993, 5.97
Catastrophic, Mississippi, Jan. 26, 1993, 5.95
Catastrophic, North Carolina, Sept. 5, 1993, 5.100
Catastrophic, Ohio, Dec. 11, 1993, 5.102
Catastrophic, Rhode Island, Feb. 27, 1993, 5.96
Catastrophic, Texas, Aug. 21, 1993, 5.100
Florida, 1993, 5.27, 6.33
Hawaii, 1993, 2.28
Illinois, 1993, 1.31
New York, 1993, 5.27
New York, May, 1993, 6.90
Ohio, 1993, 2.29
Virginia, 1993, 3.28
APARTMENT COMPLEX FIRES
California, 1993, 2.28
New Jersey, 1993, 1.32
ARIZONA
Athletic complex fire, 1993, 5.30
Catastrophic dwelling fire, Nov. 5, 1993, 5.97
Dwelling fire, 1993, 6.34
Nursing home fire, 1193, 4.29
ARKANSAS
Apartment building fire, 1993, 3.28
Catastrophic building under renovation fire, June 18, 1993, 5.104
Electric generating plant fire, Aug., 1993, 6.92
Manufacturing plant fire, Dec., 1993, 6.94
ASHES
Boiler blocked by, caused explosion, 6.92
ASPHALT
Ignited in roof fire, 6.95
ATLANTA, GA.
Stadium fire, July 20, 1993, 4.49
ATTICS
Fire spread into, 5.28, 100
Fire spread through, 4.31
Fire started in, 4.29
AUTOMOBILE FIRES
Catastrophic, Florida, March 17, 1993, 5.106
Catastrophic, Texas, July 12, 1993, 5.108
Illinois, 1993, 1.32

B

BARGE FIRES
Florida, Aug., 1993, 6.98
BEDDING
Ignited by child with cigarette lighter, 5.97
Ignited by cigarette, 2.30
Ignited by electric heater, 5.98
Ignited by match, 5.97
Ignited by medical equipment fire, 5.104
BENARICK, GLENN P.
Profile of, 1.22
BEYREIS, JAMES R.
Profile of, 5.20
BLEVE
Fire fighter fatalities related to, 4.60
BOARD AND CARE FACILITY FIRES
California, 1993, 2.30
Catastrophic, Texas, April 11, 1993, 5.105
Pennsylvania, 1993, 6.33
BOAT FIRES
Catastrophic, cabin cruiser, Ohio, May 9, 1993, 5.106
BREEDLOVE, DIANE
Profile of, 2.22
BRICE, HERMAN W.
Profile of, 3.21
BRUSH FIRES
Fire fighter injuries related to, 6.64, 66
Ignites wildland fire, 6.99
BUILDING MATERIALS
Through-penetration protection systems, 1.54
BUILDING SCENE COLUMNS
Adequacy and validity of existing fire tests, 2.14
Evaluating occupant load for egress, 1.14
NFPA 13, *Installation of Sprinkler Systems*, 1994, changes in, 3.14
NFPA 101, *Life Safety Code*, applied to industrial occupancies, 4.16
Performance-based code development, 6.16
BUILDING UNDER CONSTRUCTION FIRES
See DWELLING UNDER CONSTRUCTION FIRES
BUILDING UNDER RENOVATION FIRES
Catastrophic, dwelling, Arkansas, June 18, 1993, 5.104
BUKOWSKI, RICHARD W.
Profile of, 1.23

C

CALIFORNIA
Amusement park fire, 1993, 3.28
Apartment complex fire, 1993, 2.28
Board and care facility fire, 1993, 2.30
Catastrophic aircraft fire, Dec. 15, 1993, 5.106
Catastrophic aircraft fire, Nov. 26, 1993, 5.108
Catastrophic apartment building fire, Apr. 26, 1993, 5.96
Catastrophic apartment building fire, May 3, 1993, 5.95
Catastrophic wildland/urban interface fire, Nov. 2, 1993, 5.108
Dwelling under construction fire, 1993, 3.27
Electric power conversion facility fire, Oct., 1993, 6.92
Fatal apartment building fire, Nov., 1993, 6.89
Fatal wildland/urban interface fires, Nov., 1993, 6.99
Hotel fire, 1993, 2.28
Manufacturing plant fires, 1993, 4.31, 6.36
Naval facility incident, 1993, 3.29
Office building fire, 1993, 5.30
Shopping mall fire, 1993, 6.35
Wildland/urban interface fires, Oct., 1993, 6.99
CANADA
Detention facility fire, St. John, Brunswick, June 21, 1977, 5.50
CANDLES
Catastrophic dwelling fire caused by, 5.97
CARBON DIOXIDE SUPPRESSION SYSTEMS
Overpowered by fire, 6.94
CARPETS AND RUGS
Ignited by cutting torch, 6.97
Ignited by damaged cord, 5.28
CATASTROPHIC FIRES
U.S., 1993, study of, 5.88
CEILINGS
Collapse hampers fire fighting, 6.89
Dropped, fire started above, 6.95
Fire spread through, 6.90, 93
See also CONCEALED SPACES
CHASES
Fire spread through, 5.96, 6.89
CHEMICAL FIRES
Calcium metal/water reaction cause fire, 6.95
CHEMICAL PLANT FIRES
Catastrophic, Minnesota, Nov. 17, 1993, 5.105
Minnesota, Nov. 17, 1993, 5.105
CHESTER COUNTY, PA.
Emergency response system upgrade, 2.62
CHIEF'S BRIEFING COLUMNS
Fire department and elderly agencies focus on seniors' fire safety, 3.13
International Association of Fire Chiefs includes retirees, 6.19
Labor relations eased by seeing both sides, 2.13
Listening to fire service members, 1.13
Mission statement core of operating plan, 4.15
Networking with external groups, 5.17
CHILDREN
Playing with open-flame device, ignite catastrophic fire, 5.100
Safe Place programs include fire stations, 6.128
CHILDREN AND CIGARETTE LIGHTERS
Cause of catastrophic fire, 5.97
Cause of fire, 1.30, 2.28
CHILDREN, UNATTENDED
Catastrophic fire victims, 5.96
CHIMNEYS
Fire fighter fatalities related to collapse of, 4.66
CHINA
Manufacturing plant fire, Nov. 19, 1993, 1.48
CHRISTMAS TREE FIRES
Arizona, 1993, 6.34
Fatal, Michigan, 1993, 6.33
Utah, Dec., 1993, 6.90
CHURCH FIRES
Indiana, 1993, 4.31

1994 INDEX
VOLUME 88
NOS. 1-6

Indiana, Sept., 1993, 6.89
CIGARETTE LIGHTERS
Fire ignition source, 5.104
Incendiary fire ignition source, 5.105, 6.34
See also CHILDREN AND CIGARETTE LIGHTERS
CIGARETTES
Careless disposal of, board and care facility fire cause, 6.33
Careless disposal of, board and care facility fire cause, 2.30
Careless disposal of, catastrophic dwelling fire cause, 5.102
Careless disposal of, fatal dwelling fire cause, 1.31
Careless disposal of, store fire cause, 6.35
Careless use of, apartment complex fire cause, 1.32
Careless use of, fatal dwelling fire cause, 1.31
CLOTHING FIRES
Lamp ignites clothing, 6.33
CLUB FIRES
Florida, 1993, 5.30
Maryland, Aug., 1993, 6.89
Wisconsin, 1993, 3.29
CODES AND STANDARDS
Developing consensus for international standards, 1.36
Developing international electrical standards, 1.34
Performance-based code development, 6.16
Performance-based codes coming to North America, 3.70
See also NFPA CODES AND STANDARDS
COLLEGE BUILDING FIRES
University bell tower, West Virginia, 1993, 4.30
COMBUSTIBLE PRODUCTS
Effectiveness of product labeling systems, 1.71
COMPARTMENTATION
Through-penetration protection systems, 1.54
COMPRESSED NATURAL GAS
Vehicles fueled by, handling incidents involving, 4.84
COMPRESSED NATURAL GAS FIRES
Cylinder ruptures, causing explosion and fire, 4.30
High-pressure tanks being vented, fuel ignited by static discharge, 4.29
COMPUTER-AIDED DISPATCH
Los Angeles implements new CAD system, 2.66
CONCEALED SPACES
Attic/roof, fire started in, 4.29
Ceiling, fire started in, 6.93
Ceiling/roof, fire spread into, 5.97, 6.89
Cockloft, fire spread through, 5.98
Cockloft, fire started in, 6.90
Fire spread into, 6.36
Fire spread through, 5.95, 6.89
Floor, fire spread through, 6.93
Roof, fire spread through, 6.94, 95
Walls, fire spread into, 5.96
CONDOMINIUM FIRES
North Carolina, Sept., 1993, 6.90
CONFERENCE CENTER FIRES
New Jersey, 1993, 2.30
CONFINED SPACES
OSHA regulation aims to reduce incidents in, 5.80
Stockroom fire, 6.91
CONNECTICUT
Detention facility fire, July 7, 1977, 5.51
Store fire, 1993, 6.35
CONVEYOR BELTS
Friction between belt and roller ignites fire, 6.92
COOKING AND HEATING EQUIPMENT
See HEATING AND COOKING EQUIPMENT FIRES
CROWDED BUILDINGS
Factor in catastrophic fire, 5.102
CUTTING AND WELDING OPERATIONS
See WELDING AND CUTTING OPERATIONS

D

DALY, WENDY L.
Profile of, 3.20
DANBURY, CONN.
Detention facility fire, July 7, 1977, 5.51
DELAWARE
Catastrophic dwelling fire, Jan. 20, 1993, 5.97
DETECTORS
Absence of, factor in catastrophic dwelling fire, 5.97
Satisfactory performance, 6.95
System not operational, factor in catastrophic apartment building fire, 5.95
DETECTORS, HEAT, SATISFACTORY PERFORMANCE, 6.90
DETECTORS, SMOKE
U.S. experience with, 5.36
DETECTORS, SMOKE, NOT A FACTOR IN FIRE
Batteries missing, 1.30, 5.96, 97, 98, 100, 102
Delayed operation, 5.28
Fire above detectors located in ceiling, 4.29, 6.95
Fire on exterior of building, 6.90
Not located in area of origin, 6.91
Not operational, 4.32
DETECTORS, SMOKE, SATISFACTORY PERFORMANCE, 1.31, 2.29, 30, 5.27, 28, 97, 100, 102, 6.33, 6.89, 90, 94
DETECTORS, SMOKE, UNSATISFACTORY PERFORMANCE, 1.31
DETENTION FACILITY FIRES
Danbury, Conn., July 7, 1977, 5.51
Fire protection in correctional facilities, 5.49
Maury County, Tenn., June 26, 1977, 5.50
Ohio, April 21, 1930, 5.54
St. John, Brunswick, June 21, 1977, 5.50
DISPATCH CENTERS
Los Angeles designs state-of-the-art center, 2.66
DOORS
Closed, limited fire spread, 5.105
Closed, limited heat, gas exposure, 6.34
Locked, hamper fire fighting operations, 2.27, 6.93
Open, fire spread through, 5.96, 100, 105, 6.95, 96
See also EXITS
DOORS, FIRE
Blocked open, fire spread through, 5.95, 6.96
Limited fire spread, 5.105
Removed, factor in fire spread, 5.95
DORMITORY FIRES
Catastrophic, Texas, April 19, 1993, 5.95
DROUGHT
Factor in wildland fires, 6.99
Factor in wildland fires, 1993, 5.108
DRUGS, ILLEGAL
Factor in catastrophic fire, 5.102
DUCTS
Deep fat fryer fire ignites grease in, 3.28
Fire spread through, 5.104
See also CHASES
DUST
Sawdust, fire spreads to combustibles from, 4.30
DWELLING FIRES
Arizona, 1993, 6.34
Florida, 1993, 4.32
Indiana, 1993, 1.30
Maryland, 1993, 1.31
Massachusetts, 1993, 6.34
Michigan, 1993, 6.33
New York, 1993, 1.31
Ohio, 1993, 1.31, 5.28
DWELLING FIRES, CATASTROPHIC
Arizona, Nov. 5, 1993, 5.97
Delaware, Jan. 20, 1993, 5.97
Florida, March 13, 1993, 5.98
Georgia, Feb. 3, 1993, 5.96
Georgia, Jan. 26, 1993, 5.97
Georgia, June 27, 1993, 5.98
Maryland, April 23, 1993, 5.98
Michigan, Feb. 17, 1993, 5.96
Michigan, Nov. 30, 1993, 5.102
New York, Aug. 28, 1993, 5.100
New York, Dec. 21, 1993, 5.102
New York, June 7, 1993, 5.98
Ohio, Dec. 22, 1993, 5.96
Ohio, Feb. 14, 1993, 5.98
Oklahoma, Sept. 21, 1993, 5.100
Pennsylvania, July 25, 1993, 5.97
South Carolina, May 23, 1993, 5.96
South Carolina, Nov. 13, 1993, 5.102
Washington, D.C., Jan. 7, 1993, 5.97
West Virginia, March 7, 1993, 5.96
DWELLING UNDER CONSTRUCTION FIRES
California, 1993, 3.27

E

EARTHQUAKES AND SUBSEQUENT FIRES
Japan, July 12, 1993, 3.89
Methodology to deter and mitigate risk of earthquake-caused fires, 3.82
San Francisco, Calif., Oct. 17, 1989, 3.88
EDITORIALS
Defining NFPA's mission for year 2000, 5.4
Fire safety implications of home security systems, 3.4
Fire safety: tough challenges, great rewards, 1.4
Homeowner responsibility for wildfire protection efforts, 2.4
NFPA joins fight against smoking, 4.4
NFPA must balance tradition, transition, 6.4
EDUCATIONAL OCCUPANCY FIRES
University bell tower, West Virginia, 1993, 4.30
See also SCHOOL FIRES
EGRESS
Evaluating occupant load for egress, 1.14
ELDERLY
Fire department and elderly agencies focus on seniors' fire safety, 3.13
ELDERLY HOUSING FIRES
See HOUSING FOR ELDERLY FIRES
ELECTRIC FIRES
Transformer arcs, ignites oil, 6.92
ELECTRIC GENERATING PLANT FIRES
Alabama, June, 1993, 6.92
Arkansas, Aug., 1993, 6.92
California, Oct., 1993, 6.92
Georgia, June, 1993, 6.92
Missouri, June, 1993, 6.92
New York, March, 1993, 6.91
ELECTRICAL EQUIPMENT FIRES
Christmas tree light bulb blows, ignites tree, 6.34
Christmas tree lights, improperly spliced, ignite tree, 6.90
Cord, damaged, ignites carpet, 5.28
Corn popper ignites wood paneling, 5.95
Curling iron, left on, ignites counter, carpet, 5.27
Dimmer switch, overloaded, ignites wall insulation, 2.30
Drying machine overheats, ignites pet food, 3.29
Electrical wall receptacle malfunctions, ignites bed and bedding, 2.28
Extension cord, joined to heater cord, overheats, ignites living room contents, 5.96
Extension cord, overloaded, ignites Christmas tree, 6.33
Extension cords overheat, ignite plastic garland, 6.35
Floodlights ignite cold air balloon, 6.35
Floodlights ignite paint tarpaulins, 4.30
Gondola motor overheats, ignites carbon brushes, 3.28
Heating blanket short-circuits, ignites, 3.30
Heating element ignites dip tank, 6.36
Lamp ignites clothing draped over it, 6.33
Light ignites stored paper, 6.94
Pump arcs, ignites fuel, 5.106, 6.98
Quartz lighting ignites oil, 6.94
Radio cord short-circuits, ignites rugs, curtains, newspapers, 1.31
UPS systems, fighting fires in, 5.33
ELECTRICAL FIRES
Bus bar malfunctions, ignites hotel fire, 2.29
Conduit in wall void ignites wood siding, 5.28
Electrical system failure ignites ceiling, 6.95
Fault in transformer vault ignites generating station, 6.91
Short circuit burns conduit, ignites rafters, 4.31
Wiring ignites insulation, 4.29
Wiring, installed incorrectly, ignites insulation, 4.32
Wiring short-circuits, ignites insulation, 3.27
ELECTRICAL SAFETY COLUMNS
Electrical standards go global, 1.34
Ensuring electrical safety in workplaces, 4.35
Fighting fires in UPS systems, 5.33
Grounding equipment to protect people and equipment, 3.36
Grounding of electrical systems, historical arguments for/against, 2.32
Portable tool safety, 6.38
ELECTROCUTION
Fire fighter fatalities related to, 4.65
ELEVATORS
Fire spread through shafts, 5.104
EMERGENCY MEDICAL SERVICE
Fairfax County, Va., Fire and Rescue Department response to CIA shooting incident, 1.77
EMERGENCY RESPONSE SYSTEMS
How to upgrade existing systems, 2.62
EVACUATIONS
Area around plastics manufacturing plant due to toxic smoke, successful, 6.93
Board and care facility, successful, 6.33
Board and care facility, unsuccessful, 5.104
High-rise office building complex, 5.104, 6.90
Hospital, successful, 5.105
School, successful, 5.28
Wildland fires, California, 2.85
Wildland/urban interface fire, 5.108
EXITS
Blocked by chair, factor in catastrophic fire, 5.102
Blocked by fire, factor in catastrophic fires, 5.100
Blocked by security bars, factor in catastrophic fire, 5.96
Inadequate exit arrangements, factor in catastrophic

1994 INDEX
VOLUME 88
NOS. 1-6

fire, 1.42
Locked and blocked, contribute to fire deaths, 1.48, 3.110
EXPLOSIONS AND FIRES
Ammonium nitrate mixing plant, Minnesota, Nov. 17, 1993, 5.105
Boat, Ohio, May 9, 1993, 5.106
Compressed natural gas cylinder ruptures, 4.30
Electric generating plant, Arkansas, Aug., 1993, 6.92
Electric generating plant, Missouri, June, 1993, 6.92
Oil storage tank, Kentucky, July 2, 1993, 5.104
Propane storage tank, North Dakota, 1993, 1.30
Refinery, Louisiana, Aug., 1993, 6.93
Ships, Florida, Aug., 1993, 6.98
Warehouse, Washington, Sept., 1993, 6.97
World Trade Center, New York, Feb. 26, 1993, 6.90
World Trade Center, New York, Feb. 26, 1993, 5.104
EXPOSURE, FIRE
Fire fighter fatalities related to, 4.67, 68, 69
Fire fighter injuries related to, 6.64
EXTINGUISHERS, DRY CHEMICAL
Successful in restaurant fire, 3.28
Unsuccessful in store fire, 6.35

F

FAIRFAX COUNTY, VIRGINIA
Fire and Rescue Department response to CIA shooting incident, 1.77
FANS
Factor in fire spread, 5.97
FIRE BARRIERS
See WALLS, FIRE
FIRE DEATHS, U.S.
Building security measures contribute to fire deaths, 3.110
Factors contributing to deaths, 3.99
FIRE LOSS, U.S.
1993 report, 5.57
FIRE PREVENTION WEEK
"Sparky" speaks out; interview with fire prevention mascot, 5.66
FIRE PRODUCTS
Fire fighter fatalities related to, 4.57, 67, 68, 69
FIRE PROTECTION
Stadium fires demonstrate unique protection problems, 4.49
FIRE PROTECTION SYSTEMS
Explosion destroyed, factor in fire spread, 5.104
High-rise buildings, design of systems for, 2.36
Water mist systems, 3.46
FIRE SAFETY
Implications of home security systems; editorial, 3.4
Performance-based fire safety design code development, 6.16
Performance-based fire safety design codes coming to North America, 3.70
Tough challenges, great rewards; editorial, 1.4
FIRE SAFETY EDUCATION
1994 Learn Not to Burn champions, 3.67
Preschoolers learn fire safety in Portland, Oregon, Head Start program, 1.67
FIRE SERVICE ADMINISTRATION
Budget negatively impacted by internal departmental conflict, 4.112
Chiefs' responsibility to network with external groups, 5.17
Labor relations eased by seeing both sides, 2.13
Leaders should encourage cooperation, 3.164
Leadership takes many forms, 2.112
Leadership: what is it? 1.96
Listening to fire service members, 1.13
Membership input to volunteer fire department decisions, 1.20
Mission statement core of operating plan, 4.15
Pride as factor in volunteer department morale, 3.18
Public information officer can improve media coverage, 6.25
Volunteer training accomplished with flexibility, technology, 5.18
FIRE SERVICE APPARATUS AND EQUIPMENT
Fire fighter fatalities related to, 4.57, 61, 63, 66, 69
Fire fighter injuries related to, 6.65
FIRE SERVICE OPERATIONS
Fire fighting challenges of San Francisco, Calif., fire department, 3.119
FIRE SERVICE OPERATIONS HAMPERED
Access limited by burned stairs, 102
Access limited by confined space, 6.91
Access limited by locked doors, 2.27, 6.93
Access limited by stored goods, 6.96
Access limited, offshore fire, 6.98
Ceiling collapse, 6.89
Chemicals prevented use of water, 6.95
Communications system disabled, 6.90
Electric power loss, 5.104, 6.90
Emergency shutdown procedure caused delay, 6.92
Energized electrical equipment concern, 6.91
Explosions of gas cylinders, 6.36
Fire operations control center damaged, 5.104
Fire protection systems damaged, 5.104
Fire spreading behind fire fighters, 6.36
Heat and smoke conditions hampered entry, 2.27
Inaccessible wildland terrain, 6.99
Information on exposure not available, 3.30
Large number of occupants hamper rescue, 5.95
Large size of building, 6.97
Local response capability limited, 3.30
Multiple exposures affected control efforts, 3.27
Propane trucks at fire site, 6.96
Remote location, 6.90
Rescue operation took precedence, 6.91
Response delayed, 4.31
Roof collapse, 6.95, 96, .97
Smoke limited vision, 6.94, 96
Standpipe connections lacking, 6.92
Steep topography, 6.99
Structural collapse, 5.95, 6.94
Structural collapse threatened, 5.30
Structural fire fighting equipment lacking, 4.31
Suppression resources in use at other fires, 6.99
Water supply inadequate, 4.30, 4.31, 5.29, 6.36, 6.90, 92, 97
Water supply piping damaged, 5.104
Window lexan layer hard to penetrate, 6.89
See also DROUGHT
See also WIND
FIRE SERVICE RESCUE AND EXTRICATION
Electric generating station fire, 6.91
Large number of occupants hampers rescue, 5.95
Office building complex fire, 6.90
FIRE TESTS
Adequacy and validity of existing tests, 2.14
FIRE WALLS See WALLS, FIRE
FIRE FIGHTER FATALITIES
Ten-year analysis, 1984-1994, 4.62
U.S., 1993 report, 4.55
Wildland fire fighting rules to prevent fire fighter fatalities, 3.33
FIRE FIGHTER INJURIES
1993 report, 6.57
FIRE FIGHTER SAFETY
Hantavirus poses health threat to wilderness fire fighters, 2.31
Wildfire personnel qualifications, NFPA standard, 1.33
Wildland fire fighting rules to prevent fire fighter fatalities, 3.33
FIRE FIGHTER TRAINING
Training for fire fighters on system operation; review of literature, 3.59
FIRES
Earthquakes as cause of
See EARTHQUAKES AND SUBSEQUENT FIRES
Myths of fire, 6.67
FIRESTOPPING
See THROUGH-PENETRATION PROTECTION SYSTEMS
FIREWATCH COLUMNS, 1.29, 2.27, 3.27, 4.29, 5.27, 6.33
FIREWORKS
Fire fighters injured by, 6.64
Misuse continues to cause fires, losses, and injuries, 4.78
FIRST RESPONSE COLUMNS
Effective leaders encourage cooperation, 3.164
Internal departmental conflict negatively impacts budgets, 4.112
Leadership takes many forms, 2.112
Leadership: what is it? 1.96
Preplanning can help withstand budget cut pressures, 5.128
Safe Place program for young people, 6.128
FLAMMABLE, COMBUSTIBLE LIQUIDS
Storage lockers for hazardous materials with characteristics of, 5.71
FLAMMABLE, COMBUSTIBLE LIQUIDS FIRES
Aircraft fuel ignited by electric arc, 5.106
Duplicating fluid spills, ignited by match, 2.30
Floor stripper vapors ignited, 5.105
Kerosene, stored, contributes to spread of catastrophic fire, 5.96
Lacquer thinner vapors ignited by pilot light, 5.104
Lantern fuel ignited by space heater, 3.28
Molotov cocktails used to ignite incendiary fire, 30
Oils, glue, dye saturated floor, increased fire spread, 6.98
Unknown liquid used to ignite plastic, 6.93
See also GASOLINE
See also LP-GAS FIRES
See also OIL
FLAMMABLE PRODUCTS
Effectiveness of product labeling systems, 1.71
FLASHOVERS
Dwelling fire, Massachusetts, 1993, 6.34
School fire, Maryland, Oct. 24, 1993, 5.105
FLOORS
Fire spread through, 5.96, 6.90
Saturated with flammable liquids, increased fire spread, 6.98
FLORIDA
Apartment building fire, 1993, 5.27, 6.33
Catastrophic dwelling fire, March 13, 1993, 5.98
Catastrophic train/truck/automobile fire, March 17, 1993, 5.106
Club fire, 1993, 5.30
Fatal dwelling fire, 1993, 4.32
Hotel fire, 1993, 2.29
Manufacturing plant fire, Nov., 1993, 6.94
School fire, 1993, 1.29
Ship fire, Aug., 1993, 6.98
Store fire, 1993, 4.30, 5.30
Store fire, Jan., 1993, 6.91
FOAM
Oil fire extinguished with, 6.94
Ship fire extinguished with, 6.98
FORKLIFT FIRES
Jammed paper leads to overheating, 6.95
Vehicle ruptures natural gas piping, 1.30
FURNISHINGS
Blocks door in catastrophic fire, 5.96
Chair ignited by smoking materials in catastrophic fire, 5.102
Hot object ignites wood table in catastrophic fire, 5.97
Ignited in catastrophic fire, 5.100
FURNITURE, UPHOLSTERED
Recliner, ignited by undetermined source, 5.100
Sofa, ignited by child playing with lighter, 5.102
Sofa, ignited by cigarette, 1.31, 5.102
Sofa, ignited by spreading fire, 5.98
Sofa, ignited by unknown cause, 5.96

G

GARAGE, PARKING, FIRES
High-rise office building complex, New York, Feb. 26, 1993, 5.104, 6.90
GAS
Natural gas, handling incidents involving vehicles fueled by, 4.84
See also COMPRESSED NATURAL GAS
GAS FIRES
Butane, leaking from stove fuel cylinder, ignites fire, 5.30
Compressed natural gas cylinder ruptures, causing explosion and fire, 4.30
Compressed natural, ignited by static discharge, 4.29
Hydrogen from chemical reaction ignites, 6.95
Hydrogen, ignited by friction when line ruptures, 6.36
LP-gas stove ignites gasoline residue on clothing, 5.97
Natural, ignited by heater when piping accidently ruptured, 1.30
Natural, ignited by hydraulic oil from split line, 3.29
Natural, ignited by roof fire, 6.35
Natural, ignites aircraft parts made of resin, 4.31
Oxygen fuels hospital fire, 5.104
See also HEATING AND COOKING EQUIPMENT FIRES
See also PROPANE
GAS FIRES AND EXPLOSIONS
Acetylene, ignited by spreading fire, 6.36
Hydrogen, ignited by power plant fire, 6.92
Natural, ignited when windows opened to vent fire, 6.64
Natural, ignites lacquer thinner vapors, 5.104
Natural, leak ignited, 5.108
Propane, ignited by spreading fire, 6.36
GAS LINES
Hydrogen, contributed fuel to fire, 6.91
Hydrogen, ruptured, ignited by friction, 6.36
Natural gas, contributed fuel to fire, 6.91
Natural gas, high pressure line leaks, causes explosion, fire, 5.108
GASOLINE
Gasoline residue on clothing ignites, 5.97
Generator spark ignites fumes, 5.106

NFPA Journal

1994 INDEX
VOLUME 88
NOS. 1-6

Molotov cocktails used to ignite incendiary fire, 30
Used to ignite incendiary fire, 5.100
See also AUTOMOBILE FIRES
See also TRUCK FIRES
GEORGIA
Catastrophic dwelling fire, Feb. 3, 1993, 5.96
Catastrophic dwelling fire, Jan. 26, 1993, 5.97
Catastrophic dwelling fire, June 27, 1993, 5.98
Electric generating plant fire, June, 1993, 6.92
Fatal dwelling fire, 1993, 1.32
Storage and recycling facility fire, March, 1993, 6.97
Storage facility fire, April, 1993, 6.97
Storage facility fire, March, 1993, 6.97
GONDOLA CAR FIRES
California, 1993, 3.28
GUNSHOTS
Fire fighter fatalities related to, 4.63
Fire fighter injuries related to, 6.64
GYMNASIUM FIRES
University, Arizona, 1993, 5.30

H

HALONS
Alternative protection methods to replace halons, 6.40
HANDICAPPED PERSONS
Blind man dies when stove burner ignites bathrobe, 2.29
Life Safety Code conforms with Americans with Disabilities Act, 2.34
HAWAII
Apartment building fire, 1993, 2.28
Department store/office building fire, July, 1993, 6.91
Fatal store fire, 1993, 3.30
HAZARDOUS MATERIALS
Copper sulfate runoff diked, pumped, 6.36
Cost-effectiveness of regional hazardous materials response teams, 1.63
Isocyanate smoke requires area evacuation, 6.93
Polychlorinated biphenyls at generating plant fire, 6.92
Sodium exposure at metals processing plant fire, 6.63
Storage lockers for materials with flammable, combustible liquid characteristics, 5.71
HAZ-MAT ISSUES COLUMNS
Balancing safety and international economic development, 4.19
Differentiating emergencies from incidental releases, 2.18
Federal legislation may affect responders, 6.20
Networking most effective at local conferences, 1.16
Technology, public opinion, and prevention must be considered by response teams, 3.17
HEALTH CARE FACILITIES FIRES
See HOSPITAL FIRES
See NURSING HOME FIRES
HEAT DETECTORS
See DETECTORS, HEAT
HEATING AND COOKING EQUIPMENT FIRES
Butane leaks from portable stove cylinder, ignites, 5.30
Charcoal grill used in home ignites draperies, 4.32
Deep fat fryer fire ignites grease in hood and duct work, 3.28
Electric heater cord, joined to extension cord, overheats, ignites living room contents, 5.96
Electric heater ignites blanket, 5.98
Electric wall heater ignites cardboard box, 1.32
Gas heater ignites natural gas from ruptured piping, 1.36
Gas wall heater malfunctions, ignites wood framing, 5.96
Heat pump failed, 6.90
Natural gas heater, 6.64
Natural gas water heater pilot ignites lacquer thinner vapors, 5.104
Oil-fired hot air heating unit, installed incorrectly, ignites wood structure, 1.29
Pot, unattended, overheats, ignites catastrophic fires, 5.96, 98
Propane from grill tank released, ignited by spark, 3.28
Propane stove fuel contributes to fire spread, 5.96
Space heater ignites lantern fuel, 3.28
Stove burner ignites clothing, 2.29
Stove burners ignite book placed on stove, 5.27
Wood stove chimney, improperly installed, ignites paneling and supports, 5.27
See also HVAC systems
HIGH-RISE BUILDING FIRES
Apartment building, Florida, 1993, 5.27
Apartment building, New York, 1993, 5.27
Catastrophic, office building complex, New York, Feb. 26, 1993, 5.104, 6.90
Department store/offices, Hawaii, July, 1993, 6.91
Louisville, Ky., Fire Department training, 2.55
U. S. high-rise fires; systematic tracking system, 2.47
HIGH-RISE BUILDINGS
Fire protection systems for high-rises, 2.36
HISTORIC MANSION FIRES
See MANSION FIRES
HOME FIRES
See DWELLING FIRES
HOSPITAL FIRES
Catastrophic, New York, Sept. 1, 1993, 5.105
HOTEL FIRES
California, 1993, 2.28
Catastrophic, Illinois, March 16, 1993, 5.95
Florida, 1993, 2.29
New Jersey, 1993, 2.30
HOUSING FOR ELDERLY FIRES
Illinois, 1993, 1.31
HVAC SYSTEMS
Fire spread through, 5.104
Roof-mounted, fire spread to, 6.35
Sprinklers blocked by, 2.30

I

ILLINOIS
Catastrophic hotel fire, March 16, 1993, 5.95
Coal preparation plant fire, Dec., 1993, 6.93
Fatal apartment fire, 1993, 1.31
Manufacturing plant fire, May, 1993, 6.94
Mill fire, Aug., 1993, 6.94
Store fire, 1993, 1.32
Warehouse fire, Aug., 1993, 6.96
Warehouse fire, Jan., 1993, 6.96
INCENDIARY (SUSPICIOUS) FIRES
Apartment building, California, Nov., 1993, 6.89
Apartment building, New York, 1993, 5.27
Catastrophic, apartment building, California, May 3, 1993, 5.95
Catastrophic, apartment building, North Carolina, Sept. 5, 1993, 5.100
Catastrophic, apartment building, Rhode Island, Feb. 27, 1993, 5.96
Catastrophic, board and care facility, Texas, April 11, 1993, 5.105
Catastrophic, dwelling, Michigan, Nov. 30, 1993, 5.102
Catastrophic, dwelling, Oklahoma, Sept. 21, 1993, 5.100
Catastrophic, high-rise building complex, New York, Feb. 26, 1993, 5.104, 6.90
Catastrophic, wildland/urban interface, California, Nov. 2, 1993, 5.108
Club, Florida, Jan., 1993, 6.91
Dwelling, Massachusetts, 1993, 6.34
Manufacturing plant, Michigan, Jan., 1993, 6.95
Manufacturing plant, Michigan, June, 1993, 6.93
Office building, California, 1993, 5.30
Office building, Washington, 1993, 2.29
Secondary school, Florida, 1993, 1.29
Storage facility, Massachusetts, 1993, 2.27
Store, Florida, 1993, 5.30
Store, Mississippi, 1993, 1.32
Warehouse, Indiana, July, 1993, 6.96
Warehouse, Massachusetts, Nov., 1993, 6.97
Wildland fire, California, Nov., 1993, 6.99
Wildland fire, California, Oct., 1993, 6.99
INDIANA
Catastrophic truck fire, March 20, 1993, 5.106
Church fire, 1993, 4.31
Church fire, Sept., 1993, 6.89
Dwelling fire, 1993, 1.30
Warehouse fire, July, 1993, 6.96
INDUSTRIAL OCCUPANCIES
Causes of fires in, 4.40
NFPA 101, *Life Safety Code*, applied to, 4.16
NFPA 101, *Life Safety Code*, is key to fire safety, 4.36
See also MANUFACTURING PLANTS
INSTITUTIONAL OCCUPANCIES
See separately listed occupancies
INSULATION
Cellulose, ignited by wiring, 4.29
Fiber board, ignited by welding, 6.94
Oil-soaked, ignites, 6.92
Styrofoam, ignited by welding, 6.93
Urethane foam, ignited by short-circuit, 3.27
INTERIOR FINISHES
Fuel catastrophic fires, 5.95, 96, 98, 102, 105
INTOXICATION
See ALCOHOL (BEVERAGE)
IRVING, TEXAS
Stadium fire, October 13, 1993, 4.49

J

JAPAN
Earthquake and subsequent fire, July 12, 1993, 3.89
JUVENILE FIRESETTING
Cause of mill complex fire, 6.98
Cause of store fire, 1.32

K

KADER INDUSTRIAL CO. (THAILAND) FIRE
Investigative report, 1.42
KANSAS
Aircraft hangar fire, July, 1993, 6.96
KENTUCKY
Catastrophic storage tank fire, July 2, 1993, 5.104
Fatal manufactured home fire, 1993, 4.32, 5.27

L

LARGE-LOSS FIRES, U.S.
1993, Study of, 6.84
LARGE-LOSS-OF-LIFE FIRES
China (toy manufacturing plant), Nov. 19, 1993, 1.48
Thailand (toy manufacturing plant), May 10, 1993, 1.42
LIFE SAFETY CODE
Application to industrial occupancies, 4.16
Industrial fire safety depends on code compliance, 4.36
New code has user-friendly language, conforms with Americans with Disabilities Act, 2.34
LIGHTNING
Cause of church fire, 6.89
Cause of historic mansion fire, Pennsylvania, 1994, 4.31
LIQUEFIED NATURAL GAS
Vehicles fueled by, handling incidents involving, 4.84
LOS ANGELES, CA.
State-of-the-art fire department dispatch center, 2.66
LOUISIANA
Catastrophic refinery fire, Aug. 2, 1993, 5.105, 6.93
Race track fire, Dec., 1993, 6.89
Sawmill fire, 1993, 5.29
LOUISVILLE, KY.
Fire department and elderly agencies focus on seniors' fire safety, 3.13
Fire department training for high-rise fires, 2.55
LP-GAS FIRES
Stove ignites gasoline residue on clothing, 5.97

M

MAINE
Fatal manufactured home fire, 1993, 1.31
MANSION FIRES
Pennsylvania, 1993, 4.31
Utah, Dec., 1993, 6.90
MANUFACTURED HOME FIRES
Kentucky, 1993, 4.32, 5.27
Maine, 1993, 1.31
MANUFACTURING PLANT FIRES
Adhesive, Ohio, 1993, 5.29
Aircraft, California, 1993, 4.31
Aluminum, Illinois, Aug., 1993, 6.94
Ammonium nitrate mixing, Minnesota, Nov. 17, 1993, 5.105
Boats, Massachusetts, 1993, 1.29
Causes, 4.40
Circuit boards, California, 1993, 6.36
Coal preparation, Illinois, Dec., 1993, 6.93
Furniture, Virginia, Feb., 1993, 6.93
High-energy fuel, Wyoming, 1993, 3.30
Magnets, Pennsylvania, Dec., 1993, 6.95
Maintenance shop, California, 1993, 4.31
Metal extrusion, South Carolina, Jan., 1993, 6.95
Metal storage lockers, Michigan, Jan., 1993, 6.95
Metals processing, Newton, Mass., Oct. 25, 1993, 6.63
Paper and liner board, Florida, Nov., 1993, 6.94
Pet food, Utah, 1993, 3.29
Plastic auto bumpers, Michigan, June, 1993, 6.93
Plastic shower doors, Washington, Jan., 1993, 6.95
Poultry processing, Arkansas, Dec., 1993, 6.94
Poultry processing, Missouri, June, 1993, 6.93
Poultry processing, Pennsylvania, Feb., 1993, 6.95
Poultry processing, Texas, July, 1993, 6.94
Printing, May, 1993, 6.94
Rock processing, Wisconsin, 1993, 6.36
Shoe manufacturing, New York, Dec., 1993, 6.98
Steel, Oregon, 1993, 3.29
Toys, China, Nov. 19, 1993, 1.48
Toys, Thailand, May 10, 1993, 1.42

1994 INDEX
VOLUME 88
NOS. 1-6

MARYLAND
Catastrophic dwelling fire, Apr. 23, 1993, 5.98
Catastrophic school fire, Oct. 24, 1993, 5.105
Catastrophic truck fire, Jan. 16, 1993, 5.108
Club fire, Aug., 1993, 6.89
Fatal dwelling fire, 1993, 1.31
MASSACHUSETTS
Fatal dwelling fire, 1993, 6.34
Manufacturing plant fire, 1993, 1.29
Manufacturing plant fire, Oct. 25, 1993, 6.63
Restaurant fires, Wayside Inn, 1955, 1965, 6.75
Storage facility fire, 1993, 2.27
Warehouse fire, Nov., 1993, 6.97
MATCHES
Bedding ignited by, 5.97
Draperies ignited by, 5.104
MATTRESSES
See BEDDING
MAURY COUNTY, TENN.
Detention facility fire, June 26, 1977, 5.50
MICHIGAN
Catastrophic apartment building fire, Feb. 28, 1993, 5.95
Catastrophic dwelling fire, Feb. 17, 1993, 5.96
Catastrophic dwelling fire, Nov. 30, 1993, 5.102
Fatal dwelling fire, 1993, 6.33
Manufacturing plant fire, Jan. 1993, 6.95
Manufacturing plant fire, June, 1993, 6.93
Store fire, 1993, 4.30
Warehouse fire, 1993, 6.34
MILL FIRES
Furniture, Virginia, Feb., 1993, 6.93
Paper mill warehouse, Michigan, 1993, 6.34
Sawmill, Louisiana, 1993, 5.29
Shoe manufacturing, New York, Dec., 1993, 6.98
MINNESOTA
Catastrophic apartment building fire, Nov. 10, 1993, 5.97
Catastrophic gas pipeline fire, July 22, 1993, 5.108
Catastrophic manufacturing plant/storage facility fire, Nov. 17, 1993, 5.105
MISSISSIPPI
Catastrophic apartment building fire, Jan. 26, 1993, 5.95
Store fire, 1993, 1.32
MISSOURI
Electric generating plant fire, June, 1993, 6.92
Manufacturing plant fire, June, 1993, 6.93
MOORE, WAYNE D.
Profile of, 4.23
MULTI-AGENCY RESPONSE
Ship fire, 6.98

N

NACHBAR, MARY
Profile of, 5.21
NATURAL GAS
See GAS
NEW BRUNSWICK, CANADA
Detention facility fire, June 21, 1977, 5.50
NEW JERSEY
Apartment complex fire, 1993, 1.32
Hotel/conference center fire, 1993, 2.30
NEW MEXICO
Aircraft fire and crash, Sept., 1993, 6.98
NEW YORK
Apartment building fire, 1993, 5.27
Apartment building fire, May, 1993, 6.90
Catastrophic dwelling fire, Aug. 28, 1993, 5.100
Catastrophic dwelling fire, Dec. 21, 1993, 5.102
Catastrophic dwelling fire, June 7, 1993, 5.98
Catastrophic high-rise complex fire, Feb. 26, 1993, 5.104, 6.90
Catastrophic hospital fire, Sept. 1, 1993, 5.105
Electric generating plant fire, March, 1993, 6.91
Fatal dwelling fire, 1993, 1.31
Mill complex fire, Dec., 1993, 6.98
Store fire, April, 1993, 6.91
Warehouse fire, 1993, 1.30
NEWTON, MASSACHUSETTS
Metals processing plant fire, Oct. 25, 1993, 6.63
NFPA
Defining NFPA's mission for year 2000, 5.4
Fall meeting 1994, preview, 5.77
Financial report, 1993, 4.47
NFPA joins fight against smoking, 4.4
Organization must balance tradition, transition, 6.4
NFPA ANNUAL MEETING, NINETY-EIGHTH
Highlights of 1994 meeting, 4.71
Preview, 2.71
NFPA CODES AND STANDARDS
NFPA 13, *Installation of Sprinkler Systems*, 1994, changes in, 3.14
NFPA 101, *Life Safety Code*, applied to industrial occupancies, 4.16
NFPA 101, *Life Safety Code*, has user-friendly language, conforms with Americans with Disabilities Act, 2.34
NFPA 101, *Life Safety Code*, is key to industrial fire safety, 4.36
Relationship to international standards, 1.36
Water mist suppression standard under development, 3.53
Wildfire personnel qualifications, 1.33
NORTH CAROLINA
Catastrophic apartment building fire, Sept. 5, 1993, 5.100
Condominium complex fire, Sept., 1993, 6.90
NORTH DAKOTA
Restaurant fire, 1993, 3.28
Storage facility fire, 1993, 1.30
NURSING HOME FIRES
Arizona, 1993, 4.29

O

OCCUPANT LOAD
Evaluating occupant load for egress, 1.14
OCCUPATIONAL SAFETY AND HEALTH ADMINISTRATION (OSHA)
Confined space incidents target of new regulation, 5.80
OFFICE BUILDING FIRES
California, 1993, 5.30
Catastrophic, New York, Feb. 26, 1993, 5.104, 6.90
Hawaii, July, 1993, 6.91
Washington, 1993, 2.29
OHIO
Apartment building fire, 1993, 2.29
Catastrophic apartment building fire, Dec. 11, 1993, 5.102
Catastrophic boat fire, May 9, 1993, 5.106
Catastrophic dwelling fire, Dec. 22, 1993, 5.96
Catastrophic dwelling fire, Feb. 14, 1993, 5.98
Detention facility fire, April 21, 1930, 5.54
Fatal dwelling fire, 1993, 1.31, 5.28
Manufacturing plant fire, 1993, 5.29
Storage facility fire, 1993, 2.27
OIL
Coolant oil ignites, fuels fire, 6.94
Crude oil vapors ignited by cigarette lighter, 5.104
Floor saturated with, increased fire spread, 6.98
Hydraulic oil sprayed onto furnace ignites gas, 3.29
Lubricant oil leaks, fuels fire, 6.92
Overheated oil in transformer explodes, ignites, 6.92
OKLAHOMA
Catastrophic dwelling fire, Sept. 21, 1993, 5.100
OPENINGS
Fire spread through, 6.93
Through-penetration protection systems, 1.54
OREGON
Manufacturing plant fire, 1993, 3.29
School fire, 1993, 5.28
Warehouse fire, 1993, 3.27
OXYGEN
Fuels hospital fire, 5.104

P

PAPER
Incendiary fire started in shredded paper, 6.97
Rolled paper fuels paper mill fire, 6.34
Scrap paper jams forklift, ignites fire, 6.95
Stored paper fuels fire, 6.95
Stored paper ignited by light, 6.94
PENNSYLVANIA
Board and care facility fire, 1993, 6.33
Catastrophic dwelling fire, July 25, 1993, 5.97
Historic mansion fire, 1993, 4.31
Manufacturing plant fire, Dec., 1993, 6.95
Manufacturing plant fire, Feb., 1993, 6.95
Store fire, 1993, 6.35
PESHTIGO, WIS.
Wildland/urban interface fire, 1871, 2.86
POLYCHLORINATED BIPHENYLS (PCBs)
Haz-mat response at generating plant fire, 6.92
PORTLAND, OREGON
Preschoolers learn fire safety in Head Start program, 1.67
PRISON FIRES
See DETENTION FACILITY FIRES
PRODUCT LABELS
Effectiveness of labeling systems for flammable and combustible products, 1.71
PROFILE COLUMNS
Benarick, Glenn P., 1.22
Beyreis, James R., 5.20
Breedlove, Diane, 2.22
Brice, Herman W., 3.21
Bukowski, Richard W., 1.23
Daly, Wendy L., 3.20
Moore, Wayne D., 4.23
Nachbar, Mary, 5.21
Renfrew, Henry W., 4.22
Sharry, John, 6.26
Simmons, Philip, 2.23
Testa, William L., 6.27
PROPANE
Cylinder ruptures when overfilled, 3.30
Cylinders ignited by spreading fire, 6.36
Fuel from grill tank released, ignited by spark, 3.28
Stove fuel contributes to spread of catastrophic fire, 5.96
Tank explodes, starts fire, 1.30
Tank trucks at fire site hampered fire fighting, 6.96
Tanks protected in manufacturing plant fire, 6.95
PUBLIC ASSEMBLY OCCUPANCIES
See separately listed occupancies

R

RACE TRACK FIRES
Louisiana, Dec., 1993, 6.89
RAILROAD ROLLING STOCK FIRES
Catastrophic, passenger train collision, Florida, March 17, 1993, 5.106
RECREATION FACILITY FIRES
Amusement park, California, 1993, 3.28
Athletic complex, Arizona, 1993, 5.30
REFINERIES, OIL, FIRES
Catastrophic, Louisiana, Aug. 2, 1993, 5.105, 6.93
Utah, 1993, 6.36
RENFREW, HENRY W.
Profile of, 4.22
RESCUE
See FIRE SERVICE RESCUE AND EXTRICATION
RESIDENTIAL FIRES
See APARTMENT BUILDING FIRES
See APARTMENT COMPLEX FIRES
See CONDOMINIUM FIRES
See DWELLING FIRES
See MANUFACTURED HOME FIRES
RESTAURANT FIRES
North Dakota, 1993, 3.28
Wayside Inn fires, Massachusetts, 1955, 1965, 6.75
Wisconsin, 1993, 3.29
RHODE ISLAND
Catastrophic apartment building fire, Feb. 27, 1993, 5.96
ROOFS
Collapse damages equipment, 6.94
Collapse hampers fire fighting, 6.95, 96, 97
Collapse spreads fire, 6.95
Fire spread across, 5.98, 6.93
Fire spread through, 4.31
Fire started in, 4.29
Ignited by gas-fueled fire, 6.35
Insulation ignited by welding, 6.94
Layer ignited, 6.95
Noncombustible, limited fire spread, 6.97
Plywood subroof spreads fire, 6.94
Roofer's torch ignites roof, 3.29
Tar on roof contributes to fire spread, 6.93, 94, 95
Tar paper ignited by torch, 6.96
"Tudor" soffit allowed fire spread, 6.90
Wood, factor in wildland fire spread, 6.99
Wood-and-tar roof ignited by torch, 6.95
RUBBISH AND TRASH
Cigarettes ignite fire in trash barrel, 6.35
Fire ignited in basement debris, 5.98
Fire ignited in trash container, 5.27
RURAL FIRES
Prevention is shared responsibility of citizens, fire service, government, 5.35

S

SAN FRANCISCO, CALIF.
Earthquake and subsequent fires, October 17, 1989, 3.88
Fire fighting challenges of city fire department, 3.119
SCHOOL FIRES
Catastrophic, elementary, Maryland, Oct. 24, 1993, 5.105
Middle, Oregon, 1993, 5.28

NFPA Journal

1994 INDEX

VOLUME 88

NOS. 1-6

Secondary, Florida, 1993, 1.29
Secondary, Tennessee, 1993, 2.30
SECURITY PROVISIONS
Building security measures contribute to fire deaths, 3.110
Fire safety implications of home security systems, 3.4
Security bars, factor in catastrophic fires, 5.95, 96
SHARRY, JOHN
Profile of, 6.26
SHIP FIRES
Catastrophic, tanker, Texas, Oct. 9, 1993, 5.108
Florida, Aug., 1993, 6.98
SHOPPING MALL FIRES
California, 1993, 6.35
SIMMONS, PHILIP
Profile of, 2.23
SMOKE DETECTORS
See DETECTORS, SMOKE
SMOKE INHALATION
Fire fighter injuries related to, 6.64
SMOKING MATERIALS
Careless disposal of, catastrophic fire cause, 5.102
NFPA joins fight against smoking, 4.4
See also CIGARETTES
SOUTH CAROLINA
Catastrophic dwelling fire, May 23, 1993, 5.96
Catastrophic dwelling fire, Nov. 13, 1993, 5.102
Manufacturing plant fire, Jan., 1993, 6.95
SPONTANEOUS IGNITION
Oil and solvent soaked rags, 3.27
Oil-soaked rags, 4.31
SPRINKLER SYSTEMS
New technology of sprinkler systems, 3.38
NFPA 13, *Installation of Sprinkler Systems*, 1994, changes in, 3.14
Training for fire fighters on system operation; review of literature, 3.59
SPRINKLER SYSTEMS NOT A FACTOR IN FIRE
Fire on exterior of building, 6.35
Local systems only, 6.94
Not located in area of origin, 6.93
Not operational, 6.92, 97, 98
Water supply shut off, 6.91, 95
SPRINKLER SYSTEMS, SATISFACTORY PERFORMANCE, 1.29, 30, 32, 2.27, 29, 30, 3.27, 28, 29, 4.29, 30, 31, 5.29, 30, 105, 6.33, 34, 35, 93, 95
SPRINKLER SYSTEMS, UNSATISFACTORY PERFORMANCE
Deluge system, activated after water outage, caused major damage, 3.29
Did not operate, 6.90
Dry-pipe system failed to operate, 6.96
Failed to control fire, 6.96
HVAC equipment blocked sprinklers, 2.30
Overpowered by fire, 6.91, 93, 94, 97
System damaged by explosion, 6.90, 92
ST. JOHN, NEW BRUNSWICK
Detention facility fire, June 21, 1977, 5.50
STADIUM FIRES
Atlanta and Texas fires demonstrate unique protection problems, 4.49
STAIRWAYS
Catastrophic fires spread up, 5.95, 96, 97, 98, 100, 102, 104
STANDARDS
See CODES AND STANDARDS
STANDPIPE SYSTEMS
Lack of connections hampers fire fighting, 6.92
Water supply damaged by explosion, 4.104
STORAGE FACILITIES FIRES
Catastrophic, ammonium nitrate storage silos, Minnesota, Nov. 17, 1993, 5.105
Mini-storage facility, Ohio, 1993, 2.27
Plastic storage and recycling, Georgia, March, 1993, 6.97
Propane storage tank, North Dakota, 1993, 1.30
Shoe distribution and storage facility, 1993, 2.27
See also TANK STORAGE FACILITIES FIRES
See also WAREHOUSE FIRES
STORE FIRES
Automobiles, Illinois, 1993, 1.32
Automobiles, New York, April, 1993, 6.91
Department, Hawaii, July, 1993, 6.91
Department, Mississippi, 1993, 1.32
Department, Tennessee, Oct., 1993, 6.91
Drug, Pennsylvania, 1993, 6.35
Flea market, Florida, Jan., 1993, 6.91
Grocery, Florida, 1993, 5.30
Hardware and building supplies, Florida, 1993, 4.30
Hardware, Hawaii, 1993, 3.30
Liquor, Wisconsin, 1993, 3.29
Natural gas refueling station, Michigan, 1993, 4.30
Shopping mall, California, 1993, 6.35
Sporting goods, Connecticut, 1993, 6.35
Trucks, Texas, 1993, 4.29
STRUCTURAL COLLAPSE
Fire fighter fatalities related to, 4.57, 64, 67
Fire fighter injuries related to, 6.63, 65
Hampers fire fighting, 6.94
Hampers fire fighting in athletic complex fire, 5.30
Potential of collapse hampered fire fighting, 6.36
SUPPRESSION SYSTEMS
Carbon dioxide, overpowered by fire, 6.94
Catastrophic fires, 1.05, 4.104
Water mist systems, 3.46
See also SPRINKLER SYSTEMS

T

TANK STORAGE FACILITIES FIRES
Catastrophic, Kentucky, July 2, 1993, 5.104
TANK TRUCK FIRES
Catastrophic, Florida, March 17, 1993, 5.106
Catastrophic, West Virginia, May 11, 1993, 5.108
TAR
Roofing tar spread fire, 6.93, 94, 95
TENNESSEE
Detention facility fire, June 26, 1977, 5.50
Secondary school fire, 1993, 2.30
Store fire, Oct., 1993, 6.91
TESTA, WILLIAM L.
Profile of, 6.27
TEXAS
Aircraft crash fire, April, 1993, 6.98
Catastrophic apartment building fire, Aug. 21, 1993, 5.100
Catastrophic automobile fire, July 12, 1993, 5.108
Catastrophic board and care facility fire, Apr. 11, 1993, 5.105
Catastrophic dormitory fire, Apr. 19, 1993, 5.95
Catastrophic ship fire, Oct. 9, 1993, 5.108
Manufacturing plant fire, July, 1993, 6.94
Special property fire, 1993, 4.29
Warehouse fire, 1993, 4.32
Warehouse fire, June, 1993, 6.96
Warehouse fire, Nov., 1993, 6.95
THAILAND
Catastrophic manufacturing plant fire, May 10, 1993, 1.42
THROUGH-PENETRATION PROTECTION SYSTEMS
Update on systems, 1.54
TORCHES
Acetylene, ignites concealed space fire, 6.93
Cutting, ignites ammonium nitrate powder, 5.105
Cutting, ignites cardboard, 6.97
Cutting, ignites carpets, 6.97
Newspaper, ignites wood joists, 5.96
Roofer's, ignites roof, 3.29
Roofing, ignites roof, 6.95
Roofing, ignites wood roof members, 6.96
Welding, ignites polyurethane mats, 5.30
TRAINS
See also RAILROAD ROLLING STOCK FIRES
TRUCK FIRES
Alternative fuel pick-up, Texas, 1993, 4.29
Catastrophic, Indiana, March 20, 1993, 5.106
Catastrophic, Maryland, Jan. 16, 1993, 5.108
Michigan, 1993, 6.34
Tractor trailer, Illinois, Aug., 1993, 6.96
See also TANK TRUCK FIRES

U

UNITED STATES
Catastrophic fires, 1993, 5.88
Fire deaths affected by building security measures, 3.110
Fire deaths, factors contributing to, 3.99
Fire losses, 1993, 5.57
Fire fighter fatalities, 1993, 4.55
Fire fighter injuries, 1993, 6.57
Large-loss fires, 6.84
Smoke detector experience of, 5.36
UNIVERSITY BUILDING FIRES
See COLLEGE BUILDING FIRES
UPS (uninterruptible power supply)
Fighting fires in system, 5.33
UTAH
Dwelling fire, Dec., 1993, 6.90
Manufacturing plant fire, 1993, 3.29
Refinery fire, 1993, 6.36
UTILITIES
Electricity shut off for nonpayment, factor in catastrophic fire, 5.97
Gas shut off for nonpayment, factor in catastrophic fire, 5.96
Water shut off for nonpayment, factor in catastrophic fire, 5.96

V

VACANT BUILDING FIRES
Manufacturing mill complex, New York, Dec., 1993, 6.98
VAPORS, FLAMMABLE
Aircraft fuel vapors ignited by molten copper, 5.106
Flammable liquid vapors ignite flash fire, 5.29
Floor stripper vapors ignited, 5.105
Lacquer thinner vapors ignited by pilot light, 5.104
Oil vapors ignited by cigarette lighter, 5.104
VEHICLE FIRES
Alternative-fuel vehicle, 4.29
Bomb explosion ignites multiple vehicles, 5.104, 6.90
Gondola car, 3.28
See also SHIP FIRES
VEHICLES
Natural-gas-fueled, handling incidents involving, 4.84
VENTILATION
Closed windows allow vapors to accumulate, 5.104, 105
Fire spread by, 5.97
Window lexan layer hard to penetrate, 6.89
See also HVAC SYSTEMS
VERTICAL OPENINGS
See STAIRWAYS
VIRGINIA
Apartment building fire, 1993, 3.28
Manufacturing plant fire, Feb., 1993, 6.93
VOIDS
See CONCEALED SPACES
VOLUNTEER VIEWS COLUMNS
Changes in fire services difficult, but necessary, 4.20
Flexibility, technology meet increased need for training, 5.18
Membership input to department decisions, 1.20
Pride keeps morale high, 3.18
Public information officer can improve media coverage, 6.20
Recruiting and retaining volunteers, 2.20

W

WALLS, FIRE
Contained fire spread, 5.30, 98, 102, 105, 6.93, 97
Explosion rips open, 6.90
Fire spread over, 6.93
WAREHOUSE FIRES
Carpet and furniture, Georgia, March, 1993, 6.97
Carpet, Georgia, April, 1993, 6.97
Carpet, siding, flooring warehouse, Texas, 1993, 4.32
Cold-storage foods, Illinois, Aug., 1993, 6.96
Cold-storage fruit, Oregon, 1993, 3.27
Cosmetics and pharmaceuticals, New York, 1993, 1.30
Hops, Washington, Sept., 1993, 6.97
Magazines, Illinois, Jan., 1993, 6.96
Paper, Massachusetts, Nov., 1993, 6.97
Paper mill, Michigan, 1993, 6.34
Paper, Texas, Nov., 1993, 6.95
Peanuts, Texas, June, 1993, 6.96
Picture tubes, Indiana, July, 1993, 6.96
WASHINGTON
Manufacturing plant fire, Jan., 1993, 6.95
Office building fire, 1993, 2.29
Warehouse fire, Sept., 1993, 6.97
WASHINGTON, D.C.
Catastrophic dwelling fire, Jan. 7, 1993, 5.97
WATER MIST SUPPRESSION SYSTEMS
Design principles of system, 3.46
WAYSIDE INN FIRES
After two fires, suppression devices were installed, 6.75
WELDING AND CUTTING OPERATIONS
Cause of apartment complex fire, 2.28
Ignites fiber board insulation, 6.94
Ignites styrofoam insulation, 6.93
Torch ignites ammonium nitrate powder, 5.105
Torch ignites cardboard, 6.97
Torch ignites carpets, 6.97
Torch ignites polyurethane mats, 5.30
WEST VIRGINIA
Catastrophic dwelling fire, March 7, 1993, 5.96
Catastrophic truck fire, May 11, 1993, 5.108
University building fire, 1993, 4.30
WILDFIRE MANAGEMENT COLUMNS
Fire, ecological friend or foe of forests, 4.33
Hantavirus poses health threat to fire fighters, 2.31

NFPA standard for wildfire personnel qualifications, 1.33
Rural fire protection: a shared responsibility, 5.35
Wildland fire fighting rules to prevent fire fighter fatalities, 3.33
WILDLAND FIRES
1993 fire season overview, 2.79
California, Nov., 1993, wildland/urban interface, 6.99
California, Oct., 1993, wildland/urban interface, 6.99
Catastrophic, California, Nov. 2, 1993, wildland/urban interface, 5.108
Evacuations for California fires, 2.85
Firewise landscaping, 2.84
Homeowner responsibility for wildfire protection efforts, 2.4
Peshtigo, Wis., wildland/urban interface, 1871, 2.86
WIND
High, intensified fire spread, 2.28, 3.29, 5.108, 6.36, 90, 98, 99
WINDOWS
Blocked by furniture, hinders escape in fatal fire, 6.33
Blocked by storage, door, factor in catastrophic fire, 5.96
Closed windows allow vapors to accumulate, 5.104, 105
Fire vented through, 5.28, 100, 102, 105, 6.34, 64
Lexan layer hampered ventilation, suppression, 6.89
Security bars contribute to fire deaths, 3.110, 5.95, 96
WISCONSIN
Catastrophic aircraft fire, Dec. 10, 1993, 5.106, 6.98
Processing plant fire, 1993, 6.36
Public assembly mixed use building fire, 1993, 3.29
WOOD AND WOOD PRODUCTS
Fire starts in sawdust, spreads to combustibles, 4.30
WYOMING
Manufacturing plant fire, 1993, 3.30

Author index

A
Anderson, Kriston L., 2.71, 5.77
B
Baden, William J., 2.84
Bailey, Dan W., 1.33, 2.31, 3.33, 4.33, 5.35
Bukowski, Richard W., 3.89
C
Callan, Michael J., 1.16, 2.18, 3.17, 4.19, 6.20
Caloggero, John M., 2.32, 3.36, 4.35, 5.33, 6.38
Campbell, Timothy R. S., 2.62
Cashman, John R., 1.63
Colonna, Guy R., 5.80
Conley, Christopher J., 3.99
D
Dale, Gary, 3.88, 119
Diment, Earl, 1.67
F
Fahy, Rita F., 3.99, 4.55
Franchuk, Darrell M., 3.59
Frantz, J. Paul, 1.71
G
Garboden, Clif, 2.34, 5.66
Gonzales, Richard, 4.64
Granito, John A., 1.96, 2.112, 3.164, 4.112, 5.128, 6.128
Grant, Casey C., 1.42, 2.86, 6.40, 75
H
Hall, John R., Jr., 2.47, 4.40, 5.36, 6.67
Hershfield, Valerie D., 4.71
Hicks, Harold D., Jr., 1.50
I
Iacone, Jay, 1.77
Isner, Michael S., 4.49
K
Karter, Michael J., 5.57, 6.57
Kelly, Edward R., 1.34
Khater, Mahmoud, 3.82
Klem, Thomas J., 1.42
Koffel, William E., 1.14, 2.14, 3.14, 4.16, 6.16
L
Lathrop, James K., 4.36
LeBlanc, Paul R., 4.55, 6.57
M
Madrzykowski, Daniel, 2.55
Main, Bruce W., 1.71
Mawhinney, J. R., 3.46
McGovern, G. J., 5.71
Miller, Alison L., 3.110
Miller, George D., 1.4, 2.4, 3.4, 4.4, 5.4, 6.4
Morgan, Stephen H., 2.75
O
O'Hara, Michael, 1.54
P
Powers, William F., 4.61
Q
Quiter, James R., 2.36
R
Rhoades, Timothy P., 1.71
Richardson, J. K., 3.70
Rudd, Merlin E., 2.66
Russo, Warren P., 1.36
S
Sanders, Russell E., 1.13, 2.13, 55, 3.13, 4.15, 5.17, 6.19
Scawthorn, Charles, 3.82, 89
Schultz, Gerald R., 3.38
Solomon, Robert E., 3.53
Stauber, Richard L., 2.79
Stittleburg, Philip C., 1.20, 2.20, 3.18, 4.20, 5.18, 6.25
Stookey, Scott A., 4.84
Sullivan, Michael J., 6.84
T
Teague, Paul E., 1.22, 36, 2.22, 3.20, 4.22, 5.20, 49, 6.26
Tremblay, Kenneth J., 1.29, 2.27, 3.27, 4.29, 5.27, 88, 6.33
V
Valala, P. T., 5.71
Vaughn, Allyn J., 2.41
W
Waggoner, W. Wayne, 3.59
Washburn, Arthur E., 4.55

Your
SELECTION SOLUTION
For
FIRE
PERSONNEL

- New and Revised Entry-Level Examinations
- Nationally Validated
- Technical Reports
- Inspection Copies Available

1-800-381-TEST (8378)

IPMA Test Services is your Selection Solution. All IPMA tests are nationally validated and many are available with study guides. You can choose from three scoring options and technical reports are available for all tests. You may also request an inspection copy of a test you are considering–pre-approved Security agreement required. Call today to receive your free 1994 catalog of IPMA Test Products and Services.

ipma Test Services
International Personnel Management Association
1617 Duke St., Alexandria, VA 22314 703-549-7100 Fax 703-684-0948

Circle No. 017 on Reader Service Card